# HCK - MOUNTING OPTIONS

MOUNTING DIRECTIONS:

1. INSTALL PANEL GASKET.
2. DROP CONTROL KNOB INTO PANEL CUTOUT.
3. INSTALL 2 MOUNTING SCREWS UNDER PANEL.
4. INSTALL SUPPLIED CABLE TO UNIT - SEE SPECIFICATIONS FOR PINOUT INFORMATION

SUPPLIED PANEL GASKET

- LOW VOLTAGE

+ HIGH VOLTAGE

⌀ 1.63

0.89

0.342

0.125 (REF.)

2x #2 SCREWS, SUPPLIED

2x ⌀ 0.094

4x R0.125

⌀ 1.250

1.200

1.010

MOUNTING PANEL CUTOUT

(SCALE 1:1)